

Network Camera Firmware

Version: V5.5.97

Release Note (External)

(2019-12-15)

| | | |
|---------------------------------------|-------------------|-------------------------|
| Firmware Basic Information | Firmware Version: | V5.5.97 build191121 |
| | SDK Version: | V5.3.6.35_build20180830 |
| | iVMS-4200 | V2.6.11.5Build180905 |

Hikvision Firmware V5.5.97 build 191121 Features

1. Improved Features

- Optimized DSP to reduce CPU occupancy.
- Fixed the issue that multi-channel live viewing will cause image stuck.

Compatibility Update

- **Milestone Enterprise 10.1a, Milestone Device Pack 8.8**
- **Milestone Corporate 10.2a, Milestone Device Pack 8.8**
- **Exacqvision:**

Version: 8.4.2.111542

- **Avigilon Control Center:**

Version: V6.0.0.24

- **Intellect V4.10.3**
- **Digifort: V7.2.1**
- **Axxon: AxxonNext-4.0.2.5237**
- **Tested NVRs:**

DS-96256NI-I24/H (baseline V4.1.63) 96000 I Series

96000NI-I Series NVR (V3.6.21)

E Series: DS-7604NI-E1 (STD)

I Series: DS-8664NI-I8

K Series: V3.4.103

Q Series: V3.4.103

-D Series: HiLook V3.4.98_180905

WiFi HiLook/HiWatch: V3.4.98_180905

DeepInmind NVR:

V4.1.31, --X, S-V2 series

V4.1.25, FA, S series

Acusense NVR: V4.1.13_180925

Note: The compatibility of IPC and NVR models in the same NVR series is the same.

- **Tested Keyboard:**

DS-1600KI V2.0.0

DS-1006KI V1.0

Customer Impact and Recommended Action

This update refers to function/compatibility improvement and will take effect automatically after the Date of Change. We are very sorry for any inconvenience of use-habit changes caused by this action. For any questions and request for this firmware, please contact our local technical support team.

Remarks:

- Hikvision reserves the right to change, alter or withdraw the above notification without prior notice.
- Product design and specifications are subject to change without prior notice.
- The Hikvision firmware may contain defects or errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.
- Hikvision is not liable for any typing or printing errors.

Hikvision Digital Technology CO., Ltd.
No. 555 Qianmo Road, Binjiang District, Hangzhou 310051,
China
Tel: +86-571-8807-5998
FAX: +86-571-8993-5635

| Supported Product List(2XX1, 2XX7) | |
|------------------------------------|----------------------------------|
| DS-2CD2D21G0 | 2MP, WDR |
| DS-2CD2T21G0-I(S)(4/6mm) | 2MP, IR, WDR, Audio/Alarm |
| DS-2CD2321G0-I/NF(2.8/4/6mm) | 2MP, IR, WDR |
| DS-2CD2121G0-I(W)(S)(2.8/4/6mm) | 2MP, IR, Wi-Fi, Audio/Alarm |
| DS-2CD2621G0-I(Z)(S) | 2MP, IR, WDR, Motorized lens |
| DS-2CD2721G0-I(Z)(S) | 2MP, IR, WDR, Motorized lens |
| DS-2CD2821G0-I(Z)(S) | 2MP, WDR, Motorized lens |
| DS-2CD2021G1-I(2.8/4/6mm)(B) | 2MP, IR, WDR |
| DS-2CD2021G1-IW(2.8/4/6mm)(B) | 2MP, IR, WDR, Wi-Fi, Audio/Alarm |
| DS-2CD2021G1-I | 2MP, IR, WDR |
| DS-2CD2021G1-I(D)W | 2MP, IR, WDR, Wi-Fi |
| DS-2CD2021G1-IDW1 | 2MP, IR, WDR, Wi-Fi |
| DS-2CD2121G1-IDW1 | 2MP, IR, WDR, Wi-Fi |
| DS-2CD2027G1-L | 2MP, ColorVu, WDR |
| DS-2CD2T27G3E-L | 2MP, ColorVu, WDR |
| DS-2CD3823G0 | 2MP, WDR |