



EUROPEAN TECHNICAL CENTER

FIRMWARE RELEASE NOTE

DS-KB6403-Wi-Fi Doorbell

V1.4.62_Build180515 Release Notes

(2018-06-05)

Device Model: DS-KB6403-Wi-Fi DS-KB6003-Wi-Fi	Firmware Version:	V2.0.4 Build 180517
---	-------------------	---------------------

Reason of Upgrade

Added or modified functions, enhance products quality and meet customers' requirements

New Features

1. Support Hikvision NVR. You can preview, record, playback and do basic configuration on NVR.
2. Support Hik-Connect configuration of motion detection area and sensitivity (DS-KB6403-Wi-Fi only).
3. Support ONVIF and ISAPI protocols.
4. Support WEB interface for preview and configuration
5. Support UPNP broadcast, when the computer and the device are in the same LAN, you can find the doorbell in the network neighborhood. Double-click to open the device WEB interface;
6. Wi-Fi pairing supports Hidden SSID.

Optimized Features

1. The pre-recording mechanism of motion detection is changed to 5s before and after the event.
2. During initial setup via Hik-Connect admin password can be set. If this step is skipped, the default password is 'admin+s/n'.
3. Optimized D/N switching and infrared effects at night.
4. When the call time is over, there will be no more prompt tone and no audio indication that the home owner is not at home.
5. Improved audio loudness.
6. Optimized trigger mechanism of connected mechanical doorbell. It can be triggered for 3s every 5 seconds (DS-KB6003-Wi-Fi only).
7. Switching off the alarm push notification will not stop motion detection recording.

Bug Fixes

1. Fixed motion detection error reporting problems.
2. Fixed failures of Wi-Fi connection.
3. Fixed online upgrade failed issues.
4. Fixed abnormal SD card status.
5. Fixed no sound in HC end recordings.
6. Fixed the issues in the Web UI section.
7. Fix the problem that button LED display color is not correct in some states.
8. Fixed device rebooting if talk is too loud for DS-KB6003-WIP.
9. Fixed incorrect pronunciation of "Wi-Fi".

Customer Impact and Recommended Action

This new firmware upgrade is to improve product performance, and will take effect automatically after upgrading from previous versions. We'd like to inform you for the above changes. Also, we are sorry for any possible inconvenience of use-habit changes caused by this action.

For questions or concerns, please contact our local technical support team.

Note:

Hikvision has all rights to alter, modify and cancel this notice.

Hikvision doesn't give any guarantee for old models' stock.

Hikvision is not liable for any typing or printing errors.

For special model's change details, please contact our local technical support team.

Hikvision Digital Technology CO., Ltd.
No. 555 Qianmo Road, Binjiang District, Hangzhou
310052, China
Tel: +86-571-8807-5998
FAX: +86-571-8993-5635

